

!! URGENT!!

Date: 14 March 2016

Subject: Luxembourg (ELLX), Luxembourg

VFR Charts not updated

Jeppesen VFR charts for Luxembourg (ELLX), Luxembourg dated 4 JUL 14 do not contain the information published in AIRAC AMDT 003/2016 (eff. 31 MAR 16).

The corrected charts will be issued in the revision of 6 MAY 16 and are attached to this Alert.


This Alert is posted on Jeppesen Web site at http://www.jeppesen.com/company/alerts/aviation-alerts.jsp).


WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS IMMEDIATELY!


If you have any questions concerning this Chart Alert, please contact Charting Technical Support at: U.S. Toll Free: 1-800-353-2107 Direct: 1-303-799-9090, Extension 5830

E-mail: ChartSupport@jeppesen.com

Chart Alerts (formerly ChartWatch Notices) are published to advise users of significant issues In Jeppesen chart data which may affect aircraft operations. These Alerts are distributed to Affected chart users and are also available on Jeppesen's Web site at www.jeppesen.com.







RWY No	Dimension (m) - Surface	TORA (m)	LDA (m)	Strength	Lights
06 24	4000 x 60 Asphalt	4000	4000	PCN 65/F/A/W/U	(

A flight plan is compulsory for all VFR flights to and from ELLX.

NORDO ACFT prohibited.

Centreline crossing closer than 11 NM from ARP should be done at 2000' MAX. If unable to comply contact LUXEMBOURG APPROACH.

Unless otherwise notified to ATC by the pilot, ACFT are expected to be ready for DEP upon reaching runway-holding position. GA ACFT departing from aprons P5 and P6 shall complete all pre-departure checks, including engine/power checks, before requesting taxi instructions to enter the manoeuvring area.

Traffic landing on RWY 06 and vacating at TWY E or D1 shall await onward clearance before entering TWY B1 due to conflicting ground traffic in opposite direction.

Radio COM Failure

- Set transponder on code 7600;
- without clearance do not enter Luxembourg CTR and land on alternate AD:
- if already cleared to join AD circuit: hold on downwind and look out for light signals from TWR;
- ACFT equipped with an onboard TEL/cellphone, dial +352 4798 2405-0 or -1 and mention last RTF channel used.

Dépôt de PLN obligatoire pour les vols en VFR vers ou en provenance de ELLX.

Interdit aux aéronefs NORDO.

Croisement de l'axe de la piste à une distance inférieure à 11 NM de l'ARP doit être fait à 2000' MAX. S'il est impossible de se conformer, contacter LUXEMBOURG APPROACH.

Sauf notification contraire au contrôle par le pilote, ACFT doit être prêt à DEP dès l'arrivée au point d'arrête RWY. GA ACFT quitter les parkings P5 et P6 doivent compléter tous les tests "pre-departure", tests du moteur/power inclus, avant de demander des instructions de roulage pour entrer dans l'aire de manoeuvre.

Trafic LDG RWY 06 et dégager via TWY E ou D1 doit attendre une clairance pour continuer avant d'entrer dans TWY B1 en raison de trafic de conflit au sol en sens opposite.

Panne Radio

- Afficher le code 7600;
- ne pas entrer dans la CTR de Luxembourg sans autorisation et atterir sur l'aérodrome de dégagement; - avec autorisation de suivre le circuit: attendre dans
- le vent arrière et faire attention aux signaux lumineux de la tour:
- les aéronefs equipés de TEL/cellulaire, marquer le numéro +352 4798 2405-0 ou -1 et mentionner le dernier canal RTF utilisé.